



PEKELILING PELABUHAN NO.29/2016
PORT CIRCULAR NO. 29/2016

DARIPADA : PENGARAH LAUT WILAYAH UTARA
 FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN
 TO : GENERAL SHIPPING COMMUNITY

TARIKH : 23 Disember 2016
 DATE : 23 December 2016

CARTA BERKAITAN : MAL 5529
 RELEVANT CHART : MAL 5529

KEDUDUKAN BARU PELAMPUNG PANDU SPECIAL MARK NO.3

Masyarakat perkapalan adalah dimaklumkan bahawa kedudukan pelampung pandu special mark No.3 untuk project Seri Tanjung Pinang (Phase II) telah diubah kepada kedudukan baru. Kedudukannya seperti berikut :-

Bil	Kedudukan Lama (Pelampung Pandu Special Mark No.3)	Kedudukan Baharu (Pelampung Pandu Special Mark No.3)
1.	Lat : 05° 27' 16.12"N Long : 100° 20'00.86"E	Lat : 05° 27' 21.96"N Long : 100° 20'27.47"E

Semua vesel diminta untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan kerja tersebut.

NEW POSITION FOR BUOYS SPECIAL MARK NO.3

Mariners are informed that the position no.3 buoy special mark for Seri Tanjung Pinang Project has been changed to a new position. Its position as follows :-

Bil	Old Position (No.3 buoy Spcecial Mark)	New Position (No.3 buoy Spcecial Mark)
1.	Lat : 05° 27' 16.12"N Long : 100° 20'00.86"E	Lat : 05° 27' 21.96"N Long : 100° 20'27.47"E

All vessels are kindly advised to keep clear of this vicinity and navigate with caution when approaching the working area.

(MOHD HAZWAN DIN BIN HASHIM)

b.p. Pengarah Laut Wilayah Utara
Director Of Marine Northern Region

"Ke Arah Negara Kelautan Elektronik"
 "Towards e-Maritime Nation"



“Ke Arah Negara Kelautan Elektronik”
“Towards e-Maritime Nation”



Cert. No : MAS 101138 (B)